
JSK URJA PHASE CUT / TRIAC DRIVER CONNECTION DIAGRAM

SINGLE CONNECTION



The line passes through the regulator or home automation, then to L.

Wire Input: Line – Brown, Neutral – Blue

Wire Output: +Vdc – Red, –Vdc – Black

Connector: No

Leading edge and trailing edge, as on the phase-cut connection diagram.

Single connection. Supply 220–230VAC.

Source wiring preserved